



# Service Bulletin

File in Section: -

Bulletin No.: PI1353

Date: November, 2014

## PRELIMINARY INFORMATION

**Subject:** Information on Incorrect Service Part Number on ECM Label


**Models:** 2015 Cadillac ATS, CTS, Escalade, XTS  
2015 Chevrolet Colorado, Corvette, Silverado, Suburban, Tahoe  
2015 GMC Canyon, Sierra, Yukon  
Equipped with 6 Cylinder Engine (RPOs LV1, LV3, LF3, LFX) or 8 Cylinder Engines (RPOs L83, L86, LT1, LT4)

The purpose of this bulletin is to inform dealers that the E92 Engine Control Module (ECM) labels have an incorrect service part number.



4010219

The incorrect service part number 12656993 as shown above for a E92 (1) label is for the 2014 model year vehicles. DO NOT use for 2015 model year vehicles.



4010244

The correct service number is 12662034 (1) as shown above. Use this service part number for 2015 model year vehicles.